



Service Bulletin

Date: 5-30-12

Service Bulletin: A.C.T. 5-12, 2 – Condenser Fuse Style Change

Models Affected: All A.C.T. Condensers

Release Date: April 2012

Action: The existing 20 amp fuse (p/n: 580-043) has been replaced with a 20 amp ATM mini fuse (p/n: 580-040) to protect each fan motor. The fuse is located inside of the condenser and is part of the internal condenser harness.