



Service Bulletin

Date: 3-12-13

Service Bulletin: A.C.T. 3-13, 1 – CR-2 Rooftop Condenser Cover Mounting Modification

Models Affected: A.C.T. CR-2 Rooftop Condenser
Serial Number 23-00101 through 23-00328

Release Date: December 2010

Action: A.C.T. has modified the mounting of the cover on rooftop condenser model CR-2. Models with the affected serial numbers will need inspected and modified.

Please refer to document, DWG-CVR-601 for the necessary modifications, instructions and required supplies.

A.C.T. will supply the necessary parts needed to complete the modifications at no cost. A.C.T. will allow a onetime fee of \$50.00 to complete this modification.

Prior approval from A.C.T. will be necessary before any modifications are made.

Please contact A.C.T. at 877-228-4247 to file a claim and/or determine if the model you own/operate is affected.