



Service Bulletin

Date: 7-30-12

Service Bulletin: A.C.T. 7-12, 1 – Condenser Fuse Size Upgrade

Models Affected: All A.C.T. Condensers Manufactured April 2012 - July 2012

Release Date: April 2012

Action: The existing 20 amp ATM mini fuse (p/n: 580-040) has been replaced with a 25 amp ATM mini fuse (p/n: 580-094) to protect each fan motor. The fuse is located inside of the condenser and is part of the internal condenser harness.